

92301676  
IN CASE OF EMERGENCY OR SPILL, CALL THE NATIONAL RESPONSE CENTER 1-800-424-8802; WITHIN CALIFORNIA, CALL 1-800-852-7559

UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No.	Manifest Document No.	2. Page 1 of 1	Information in the shaded areas is not required by Federal law.
3. Generator's Name and Mailing Address <b>Douglas Aircraft Company</b> <b>19503 S. Normandie Avenue</b> <b>For France, CA 90502</b>		Attn: <b>R. Tuell</b> Mail Code: <b>C6-59</b>	A. State Manifest Document Number <b>92301676</b>		
4. Generator's Phone <b>310-533-7928</b> or <b>(310) 533-7231</b>		B. State Generator's ID <b>HAHQ36005698</b>			
5. Transporter 1 Company Name <b>Laidlaw Environmental Services of California, Inc.</b>		C. State Transporter's ID <b>423 543</b>	D. Transporter's Phone <b>(310) 518-4700</b>		
7. Transporter 2 Company Name		E. State Transporter's ID	F. Transporter's Phone		
9. Designated Facility Name and Site Address <b>Chem-Tech Systems, Inc.</b> <b>3650 E. 26th Street</b> <b>Los Angeles, CA 90023</b>		10. US EPA ID Number <b>CAT080033681</b>	G. State Facility's ID <b>CAT080033681</b> H. Facility's Phone <b>(213) 268-5056</b>		
11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)		12. Containers No. Type	13. Total Quantity	14. Unit Wt/Vol	I. Waste Number
a. <b>Benzotriazole</b> <b>CERTIFICATE OF TREATMENT/RECYCLING</b> <b>Non-RCRA Hazardous Waste Liquid</b>		<b>001 TT</b>	<b>21720</b>	<b>P</b>	State <b>134</b> EPA/Other <b>NA</b>
b. CHEM-TECH SYSTEMS, INC. certifies that the liquid waste received with this manifest will be treated to standards mandated by the FEDERAL CLEAN WATER ACT and the Los Angeles County Sanitation					State EPA/Other
c. Districts' effluent requirements. Treatment/recycling is performed under permits granted by the California Department of Toxic Substances Control, Environmental Protection Agency, Provisions of the Resource Conservation and Recovery Act (RCRA) of 1976, and applicable federal					State EPA/Other
d. and state regulations. The generator's responsibility for this liquid waste is eliminated under both RCRA and the provision 68.					State EPA/Other
J. Additional Descriptions for Materials Listed Above <b>Tank Solution and Rinse water from pumping and cleaning of Benzotriazole Insulators</b> <b>Benzotriazole GENERAL MANAGER 97-99%</b>		K. Handling Codes for Wastes Listed Above			
15. Special Handling Instructions and Additional Information <b>Emergency Response Telephone Number: (800) 424-9300 (Chemtrec)</b> <b>DOT ERG# 31</b>					
16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of the consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable federal, state and international laws.  If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.					
Printed/Typed Name <b>Robert G. Tuell, Jr</b>		Signature <i>Robert G. Tuell, Jr.</i>		Month Day Year <b>12/13/93</b>	
17. Transporter 1 Acknowledgement of Receipt of Materials Printed/Typed Name <b>Jack L Sheffield</b>		Signature <i>Jack L Sheffield</i>		Month Day Year <b>12/13/93</b>	
18. Transporter 2 Acknowledgement of Receipt of Materials Printed/Typed Name		Signature		Month Day Year	
19. Discrepancy Indication Space					
20. Facility Owner or Operator Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19. Printed/Typed Name <b>JALEH KHORAMI</b>					
Signature <i>J. Khorami</i>		Month Day Year <b>12/13/93</b>			

DO NOT WRITE BELOW THIS LINE.

Yellow: TSDF SENDS THIS COPY TO GENERATOR WITHIN 30 DAYS.  
(Generators who submit hazardous waste for transport out-of-state, produce completed copy of this copy and send to DTSC within 30 days.)

92301676

IN CASE OF EMERGENCY OR SPILL, CALL THE NATIONAL RESPONSE CENTER 1-800-424-8802; WITHIN CALIFORNIA, CALL 1-800-852-7555

GENERATOR

TRANSPORTER

FACILITY

UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No.	Manifest Document No.	2. Page 1 of 1	Information in the shaded areas is not required by Federal law.
3. Generator's Name and Mailing Address <b>Douglas Aircraft Company</b> <b>19503 S. Normandie Avenue</b> <b>For France, CA 90502</b>		Attn: <b>R. Tuell</b> Mail Code: <b>C6-59</b>	<b>CAD08651000501676</b>		A. State Manifest Document Number <b>92301676</b>
4. Generator's Phone <b>310-533-7228</b>		or US EPA ID Number <b>CA D0000683121</b>			B. State Generator's ID <b>HAH036005698</b>
5. Transporter 1 Company Name <b>Laidlaw Environmental Services of California, Inc.</b>		8. US EPA ID Number <b>CAD0000683121</b>			C. State Transporter's ID <b>423543</b>
7. Transporter 2 Company Name					D. Transporter's Phone <b>(310) 518-4700</b>
9. Designated Facility Name and Site Address <b>Chem-Tech Systems, Inc.</b> <b>3650 E. 26th Street</b> <b>Los Angeles, CA 90023</b>		10. US EPA ID Number <b>CAT080033681</b>			E. State Transporter's ID
					F. Transporter's Phone
					G. State Facility's ID
					H. Facility's Phone <b>(213) 268-5056</b>
11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)		12. Containers No. Type	13. Total Quantity	14. Unit Wt/Vol	Waste Number
a. <b>Benzotriazole</b> <b>Non-RCRA Hazardous Waste Liquid</b>		<b>001 TT</b>	<b>21720</b>	<b>P</b>	State <b>134</b> EPA/Other <b>NA</b>
b.					State EPA/Other
c.					State EPA/Other
d.					State EPA/Other
J. Additional Descriptions for Materials Listed Above <b>Tank Solution and Rinse Water from Pumping and Cleaning Tank 554; Ultrasonic Inspections</b> <b>Benzotriazole 1-3% ; Water 97-99%</b>		K. Handling Codes for Wastes Listed Above			
15. Special Handling Instructions and Additional Information <b>Emergency Response Telephone Number: (800) 424-9300 (Chemtec)</b> <b>DOT ERG#31</b>					
16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of the consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable federal, state and international laws.  If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.					
Printed/Typed Name <b>Robert G. Tuell, Jr</b>		Signature <b>Robert G. Tuell, Jr.</b>		Month Day Year <b>12 13 93</b>	
17. Transporter 1 Acknowledgement of Receipt of Materials Printed/Typed Name <b>Jack L Sheffield</b>		Signature <b>Jack L Sheffield</b>		Month Day Year <b>12 13 93</b>	
18. Transporter 2 Acknowledgement of Receipt of Materials Printed/Typed Name		Signature		Month Day Year	
19. Discrepancy Indication Space					
20. Facility Owner or Operator Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19. Printed/Typed Name Signature Month Day Year					

DO NOT WRITE BELOW THIS LINE.

WEIGHT TICKET

VENDOR: Laidlaw

TRUCK #: 16045

DATE: 12-13-93

CONTENTS: Tank 554

water with Benzotriazole

DISPOSAL FACILITY: Chemtech

RRG 12-13-93

DRIVER: Jack Shearfield

DRUM COUNT

GALLONS

GROSS

TARE

NET

53 220 P

31 500 P

21 720 P

STATE MANIFEST DOCUMENT NUMBER: 01676 / 92301676

423543  
Truck

RRG  
12-13-93



Laidlaw Environmental Services of California, Inc.

SERVICE ORDER 92-74206  
JOB NO. 240120  
DATE 12-13-93

### TRANSPORTATION SERVICE ORDER

Transportation ID #: CAD000083121

☐ 4501 Pacheco Blvd.  
Martinez, CA 94553  
(510) 372-4800

☐ 3237 Patton Way  
Bakersfield, CA 93308  
(805) 835-5801 or  
(805) 589-4970

2013 ☒ 221 E. "D" Street  
Wilmington, CA 90744  
(310) 518-4700

Customer Name: Douglas

Telephone: \_\_\_\_\_

Billing Address: \_\_\_\_\_

Contact Person: \_\_\_\_\_

City: Torrance State CA

BOE #: \_\_\_\_\_

Job Location: Off I

Destination: Los Angeles CA

Type of Material: \_\_\_\_\_

Sales Person: \_\_\_\_\_

Generator: Douglas

EPA Number: \_\_\_\_\_

Generator ID Number (State): \_\_\_\_\_

Facility EPA NO.: \_\_\_\_\_

Disposal: LES Facility \_\_\_\_\_ Outside Facility \_\_\_\_\_ None \_\_\_\_\_

Customer P.O. 27064-H6007

Manifest # 92301676 # \_\_\_\_\_ # \_\_\_\_\_

Services Performed I removed and cleaned out back lining pit  
and two disposal site worked on truck  
worked as directed  
Returned to yard

Start Miles: 467618

End Miles: \_\_\_\_\_

Total Miles: \_\_\_\_\_

Truck No.: 16045

Trailer No: 16041T

Net Wgt: \_\_\_\_\_

Capacity: \_\_\_\_\_

Driver Time: Start (AM/PM) \_\_\_\_\_

Stop (AM/PM) \_\_\_\_\_

Gross Time \_\_\_\_\_

Meals: Start Time (AM/PM) \_\_\_\_\_

Stop (AM/PM) \_\_\_\_\_

Less Time \_\_\_\_\_

Other Time \_\_\_\_\_

Detail \_\_\_\_\_

Adj. Time \_\_\_\_\_

Driver's Name Jack Sheffield

Driver No. 61290

Total Time \_\_\_\_\_

Customer Site: Time In 7:00

Disposal Site: Time In \_\_\_\_\_

Time In \_\_\_\_\_

Time Out 11:15

Time Out \_\_\_\_\_

Time Out \_\_\_\_\_

Explanation of Time: \_\_\_\_\_

CUSTOMER AUTHORIZATION AND APPROVAL SIGNATURE: Robert B. Sullivan, Jr. 12-13-93

#### FOR ACCOUNTING ONLY

PROD CODE	DESCRIPTION	QTY	UOM	RATE	EXT	PROD CODE	DESCRIPTION	QTY	UOM	RATE	EXT
14000	TRANS		ST			24015	HAZ SOLIDS				
14000	TRANS		OT			24015	N/HAZ SOLIDS				
14000	TRANS		DT			24010	HAZ LIQUIDS				
	2ND DRIVER					24010	N/HAZ LIQUIDS				
	SUBHAULER					24020	DRUMS				
54045	LABOR					24025	SOLID SURCHG				
94065	BIN RENTAL					24025	STABILIZATION				
14000	TRANS (NO DISP)					24025	LIQ SURCHG				
14000	WASHOUT						TAXES				
14000	SCALE/CERTS						TAXES				
14000	SUBSISTENCE					34035	ANALYTICAL				
1055	TOLLS					74055	MISC CHARGES				
J465	TYVEK					74055	MISC CHARGES				
90465	BOOTS										
90465	GOGGLES										
90465	GLOVES										
90465	BIN LINERS										
70455	OTHERS										

**POTENTIAL HAZARDS****FIRE OR EXPLOSION**

Some of these materials may burn, but none of them ignites readily.

**HEALTH HAZARDS**

Contact may cause burns to skin and eyes.

Fire may produce irritating or poisonous gases.

Runoff from fire control or dilution water may cause pollution.

**EMERGENCY ACTION**

Keep unnecessary people away; isolate hazard area and deny entry.

Positive pressure self-contained breathing apparatus (SCBA) and structural firefighters' protective clothing will provide limited protection.

**CALL CHEMTREC AT 1-800-424-9300 FOR EMERGENCY ASSISTANCE.**

If water pollution occurs, notify the appropriate authorities.

**FIRE**

**Small Fires:** Dry chemical, CO<sub>2</sub>, water spray or regular foam.

**Large Fires:** Water spray, fog or regular foam.

Move container from fire area if you can do it without risk.

**Do not scatter spilled material** with high-pressure water streams.

Dike fire-control water for later disposal.

**SPILL OR LEAK**

Stop leak if you can do it without risk.

**Small Dry Spills:** With clean shovel place material into clean, dry container and cover loosely; move containers from spill area.

**Small Spills:** Take up with sand or other noncombustible absorbent material and place into containers for later disposal.

**Large Spills:** Dike far ahead of liquid spill for later disposal.

Cover powder spill with plastic sheet or tarp to minimize spreading.

**FIRST AID**

In case of contact with material, immediately flush eyes with running water for at least 15 minutes. Wash skin with soap and water.

Remove and isolate contaminated clothing and shoes at the site.